



Report ID: 335

Type: Battery Health Check

Tool: BA201 Date: 05/03/2026 5:22 PM

Shop Name: Sample Auto Repair

Phone Number: (800) 555-0100

Shop Email Address: shop@example.com


Vehicle Information	Customer Information
2014 KIA CADENZA V6, 3.3L; DOHC; 24V; DI	Name: Customer A
VIN: 2DVG V48225H682436 Odometer: 5000 miles	Phone Number: (800) 555-0199
Module No: N/A	Email: customer.a@example.com
CalID: N/A CVN: N/A	

Battery Health Check

Battery Information

Battery Type	Flooded	Rating	850 CCA
--------------	---------	--------	---------

Battery Health Result



Status	REPLACE BATTERY	Measured	520 CCA
Test Outcome	Replace the battery as soon as possible.	Internal Resistance	5.62 mΩ
State of Health (SOH)	--%	Battery Voltage	12.36 V
State of Charge (SOC)	70%	Battery Temperature	41 °C

Repair Tip

Replace the battery and retest. In some cases, a poor connection between the battery terminal and the tester clamp may affect test results. After disconnecting the battery cables, conduct an out-of-vehicle test before proceeding with the battery replacement.